

OPERATING MANUAL

KNURLING TOOL RD3/RF3 191 / 192 / 291



Please read this operating manual carefully. Correct assembly and handling of the tool will save you set-up time and allow you to achieve optimal results.

KNURLING PROFILES AND PRODUCTION PROCESS

191 / 192 series		291 series	
Machining direction	Knurling profiles on the workpiece: RAA RBL RBR RGE	Knurling profiles on the workpiece: RGE30° RGE45°	
axial	Selection of knurling wheels: 3 x AA 3 x BR 3 x BL 1 x BR / 2 x BL 1 x BL / 2 x BR	Selection of knurling wheels: 3 x AA 1 x BR15° / 2 x BL15° 1 x BL15° / 2 x BR15°	

Table 1: Knurling profiles

191 series (forming)




Fig. 1: Series 191 exploded drawing

Ordering spare parts:
Please specify the tool number and the corresponding position number (see Fig. 1).

Knurling profile	Forming production process	Knurling profile	Milling production process
RAA knurl with straight pattern		RGE left / right-hand knurl, raised points, 30°	
RBL left-hand knurl			
RBR right-hand knurl		RGE left / right-hand knurl, raised points, 45°	
RGE left / right-hand knurl, raised points, 30°			

Table 2: Manufacturing process

TOOL SETTING

1. General information

Produce a chamfer (30° – 45°) on the workpiece with a minimum width corresponding to half of the pitch of the knurling wheel on the start of the workpiece. The concentricity of the workpiece must be max. 0.03 mm.

Note: Rotation of the threaded bush CW → Setting of the profile depth
Rotation of the threaded bush CCW → Produces a reduction of the profile depth

2. Tool setting

The following points must be observed for optimal adjustment and use of the tool.

Knurling jaw assembly

Various jaws are pre-assembled depending on the tool type. Conversion between the milling machining process (291 series), forming (191 series) and forming up to a shoulder (192 series) can take place by using different jaw sets. These variants are shown in Figure 3.

Removal:

If the jaw sets must be replaced, first remove the stop screw completely (Fig. 1, Pos. 9) and loosen the three threaded pins (Fig. 3, Pos. 11). Then turn the threaded bush (Fig. 1 + 3, Pos. 1) counterclockwise (CCW) until the knurling jaws (Fig. 1 + 3, Pos. 4) can be removed individually from the guide slot.

Installation:

Vertical positioning of the tool is recommended for easier installation (pull knurling jaws upward, Fig. 3). Now slide the jaws (Fig. 1 + 3, Pos. 4) into the guide slots until the front edge of the jaw is flush with the surface of the recess facing inward (Fig. 2). Then, turn the threaded bush clockwise (CW) until the guide slot of the splined bush (Fig. 2 + 3, Pos. 14) engages in the jaws and pulls them together evenly. Screw in the stop screw again (Fig. 1, Pos. 9).

Note: With use of jaw set 291, a knurling wheel with a different spiral direction must be installed in the jaw with the negative clamping surface. (Example: 1x BL15° & 2x BR15° or 1x BR15° & 2x BL15°), (cf. Table 2, RGE 30°/45°)




Fig. 2: Jaw installation




Fig. 3: General view + jaw variants

Knurling wheel assembly

Forming (jaw set 191):

Loosen the threaded pin (Fig. 1 + 3, Pos. 6) and remove the axle pin (Fig. 1 + 3, Pos. 5). Change the knurling wheel (Fig. 3, Pos. 12) and fix it with the axle pin in the groove.
Note: Align the clamping surface of the axle pin so that it is tensioned after the tightening of the front threaded pin.

Forming up to a shoulder (jaw set 192):

Completely loosen the bearing screw (Fig. 3, Pos. 5) and remove the knurling wheels (Fig. 3, Pos. 12). Fit new knurling wheels on the bearing bush (Fig. 3, Pos. 6) and fix with the bearing screw (cf. Figure 3).

Cutting (jaw set 291):

Completely loosen the lock screw (Fig. 3, Pos. 5) and remove it with the knurling wheel (Fig. 3, Pos. 12) and the bearing bush (Fig. 3, Pos. 6). Then fit a new knurling wheel on the bearing bush and tighten screw it together with the jaw (Fig. 3, Pos. 4) with the lock screw (cf. Figure 3).

3. Centring of the tool

1. Clamp the tool holder in the machine
2. Unscrew the fastening screw (Fig. 1, Pos. 9) and threaded pins (Fig. 1, Pos. 8; Fig. 3, Pos. 11)
3. Unscrew the threaded bush (Fig. 1, Pos. 1; Fig. 3, Pos. 1) and move over the workpiece in the Z-direction
4. Close the threaded bush until the knurled wheels are in contact with the diameter of the workpiece
5. If all knurling wheels rotate with the workpiece, the tool is centred
6. Tighten the threaded (Fig. 1, Pos. 8) pins evenly
7. Open the jaws one scale mark wide with the threaded bush and move out of the component.




Fig. 4: Centring of the tool (front view)

4. Setting the profile depth

Setting of the profile depths takes place after the centring of the toolholder. This depends on the knurling process, pitch, profile and material displacement to be carried out. For this purpose, loosen the fastening screw (Fig. 1, Pos. 9) and threaded pins (Fig. 1, Pos. 8) and turn the threaded bush (Fig. 1 + 3, Pos. 1) clockwise.
Note: One scale mark corresponds to 0.05 mm, referring to the diameter

Form knurling:

Setting = material displacement – pitch
Example: Profile AA / pitch 1.0 mm / workpiece Ø 15 / free-cutting steel material
Setting = 1.0 mm – 0.4 mm = 0.6 mm
Setting on scale = $\frac{\text{Setting}}{1 \text{ scale mark}} = \frac{0.6 \text{ mm}}{0.05 \text{ mm}} = 12 \text{ scale marks}$

Cut knurling:

Setting corresponds to the half pitch $\left(\frac{p}{2}\right)$
Example: Profile AA / pitch 1.0 mm / workpiece Ø 15 / free-cutting steel material
Setting = 1.0 mm / 2 = 0.5 mm
Setting on scale = $\frac{\text{Setting}}{1 \text{ scale mark}} = \frac{0.5 \text{ mm}}{0.05 \text{ mm}} = 10 \text{ scale marks}$

Then, firmly tighten the fastening screw (Fig. 1, Pos. 9) and threaded pins (Fig. 2, Pos. 8) for fixing the diameter (observe torque table, chapter 6).
Note: In order to compensate for point 3, chapter 7 and possible thread play, adjust one additional scale mark.

APPLICATION

5. Feed rate in Z direction

After adjusting the working area and fixing the tool, the tool can be moved over the component axially in the Z-direction (Fig. 5).

The feed rate according to chapter 8 must be observed during the process. If the desired length of the knurling is reached, disengage in the opposite Z-direction.

Note: Depending on the profile and pitch which are used, the feed rate in the opposite Z-direction can be 0.5 mm to 1 mm higher than during the knurling.




Fig. 5: Feed in Z direction

The correct profile depth has been reached when the profile is knurled completely (Fig. 6, ref. 1). If the profile is not formed (Fig. 6, ref. 2), adjust the threaded bush an additional scale mark and run the workpiece through again. Running into the workpiece again is possible, because the knurling wheels catch in the existing profile.




Fig. 6: Different profile pattern

6. Manufacturer's recommendation

Replace the bearing bush (Fig. 3, Pos. 6; 192/291 series), knurling wheel (Fig. 3, Pos. 12), bearing screw (Fig. 3, Pos. 5; 192 series) and lock screw (Fig. 3, Pos. 5; 291 series) and axle pin (Fig. 3, Pos. 5) after a reasonable number of cycles, no later than upon appearance of significant wear or deviating process parameters.

Note:

- Always install knurling wheels with the same pitch
- A material displacement of min. 0.03 mm and max. 0.1 mm can arise during the cutting

Designation	Torque	Pos. no.
M3 cylinder head screw	3.5 Nm	Fig. 1, Pos. 7
M3 threaded pin	1.5 Nm	Fig. 1, Pos. 13
M4 set screw	3.5 Nm	Fig. 1, Pos. 8; Pos. 11; Fig. 1, Pos. 11
M4 Allen screw	3.5 Nm	Fig. 1, Pos. 9
M4 lock screw	3.6 Nm	Fig. 3, Pos. 5

Table 3: Torque specifications

7. Troubleshooting

Problem:	Reason / Cause:	Solution:
Profile is not completely knurled	The profile depth setting is not correct	Increase the profile depth setting (see chapter 4, Setting the profile depth)
Spangle collets on the profile (191 / 192 series)	– Residence time in the engagement too long – Tooth pitch does not reach the workpiece	– Observe residence time (3 – 10 rotations of the workpiece) – Adjust rough turn diameter and / or pitch
Finished diameter of the workpiece incorrect	– Incorrect rough turn diameter – Various influential factors not taken into consideration	– Adjust the rough turn diameter of the workpiece – Observe the workpiece deformation according to chapter 9, Table 7 – 9
Heavy material deformation at knurling end (191/192 series)	– Feed rate values not correct – Profile depth is not correct	– Adjust cutting data as specified in chapter 8 – Adjustment of profile depth = pitch (see chapter 4, Setting the profile depth)
Tooth base is knurled unevenly	Centring is not correct	Centre the tool as specified in chapter 3.

Table 4: Troubleshooting

8. Guidelines for cutting speed and feed rates

Material	Workpiece Ø [mm]	Knurling wheel Ø [mm]	Vc [m/min]	f [mm/rev]						
				Radial		Axial				
				from	to	from	to	from	to	
Free-cutting steel	<10	10/15	20	50	0.04	0.08	0.14	0.09	0.06	0.05
	10-40	15/20	25	55	0.05	0.10	0.20	0.13	0.10	0.07
	40-100	20/25	30	60	0.05	0.10	0.25	0.18	0.12	0.08
	100-250	20/25	30	60	0.05	0.10	0.30	0.20	0.13	0.09
	>250	25	30	60	0.05	0.10	0.32	0.21	0.14	0.10
Stainless steel	<10	10/15	15	40	0.04	0.08	0.12	0.08	0.05	0.04
	10-40	15/20	20	50	0.05	0.10	0.17	0.11	0.09	0.06
	40-100	20/25	25	50	0.05	0.10	0.21	0.15	0.10	0.07
	100-250	20/25	25	50	0.05	0.10	0.26	0.17	0.11	0.08
	>250	25	25	50	0.05	0.10	0.27	0.18	0.12	0.09
Brass	<10	10/15	30	75	0.04	0.08	0.15	0.09	0.06	0.05
	10-40	15/20	40	85	0.05	0.10	0.21	0.14	0.11	0.07
	40-100	20/25	45	90	0.05	0.10	0.26	0.19	0.13	0.08
	100-250	20/25	45	90	0.05	0.10	0.32	0.21	0.14	0.09
	>250	25	45	90	0.05	0.10	0.34	0.22	0.15	0.11
Aluminum	<10	10/15	25	60	0.04	0.08	0.18	0.11	0.08	0.06
	10-40	15/20	30	65	0.05	0.10	0.25	0.16	0.13	0.09
	40-100	20/25	35	70	0.05	0.10	0.31	0.23	0.15	0.10
	100-250	20/25	35	70	0.05	0.10	0.38	0.25	0.16	0.11
	>250	25	35	70	0.05	0.10	0.40	0.26	0.18	0.13

Table 5: Cutting speed and feed rate / forming

Material	Workpiece Ø [mm]	Knurling wheel Ø [mm]	Vc [m/min]	f [mm/rev]						
				Radial		Axial				
				from	to	from	to	from	to	
Free-cutting steel	<10	10/15	40	70	0.04	0.08	0.20	0.13	0.08	0.07
	10-40	15/20	50	90	0.05	0.10	0.28	0.18	0.14	0.10
	40-100	25/32/42	65	110	0.05	0.10	0.35	0.25	0.17	0.11
	100-250	25/32/42	65	110	0.05	0.10	0.42	0.28	0.18	0.13
	>250	32/42	80	130	0.05	0.10	0.45	0.29	0.20	0.14
Stainless steel	<10	10/15	22	40	0.04	0.08	0.14	0.09	0.06	0.05
	10-40	15/20	30	50	0.05	0.10	0.20	0.13	0.10	0.07
	40-100	25/32/42	35	60	0.05	0.10	0.25	0.18	0.12	0.08
	100-250	25/32/42	35	60	0.05	0.10	0.29	0.20	0.13	0.09
	>250	32/42	45	55	0.05	0.10	0.31	0.21	0.14	0.10
Brass	<10	10/15	55	100	0.04	0.08	0.22	0.14	0.09	0.08
	10-40	15/20	70	125	0.05	0.10	0.31	0.20	0.15	0.11
	40-100	25/32/42	90	155	0.05	0.10	0.39	0.28	0.18	0.12
	100-250	25/32/42	90	155	0.05	0.10	0.45	0.31	0.20	0.14
	>250	32/42	115	140	0.05	0.10	0.49	0.32	0.22	0.15
Aluminum	<10	10/15	70	120	0.04	0.08	0.12	0.08	0.05	0.04
	10-40	15/20	80	150	0.05	0.10	0.17	0.11	0.08	0.06
	40-100	25/32/42	110	140	0.05	0.10	0.21	0.15	0.10	0.07
	100-250	25/32/42	110	140	0.05	0.10	0.25	0.17	0.11	0.08
	>250	32/42	130	150	0.05	0.10	0.27	0.18	0.12	0.08

Table 6: Cutting speed and feed rate / cutting

9. Material displacement

Material	Workpiece Ø [mm]	Pitch [mm]											
		0.3	0.4	0.5	0.6	0.7	0.8	1.0	1.2	1.5	1.6	2.0	
Free-cutting steel	5	0.08	0.14	0.18	0.22	0.27	0.29	0.35	0.50	–	–	–	–
	15	0.08	0.14	0.18	0.23	0.30	0.40	0.44	0.50	0.60	0.65	0.70	–
	25	0.08	0.15	0.23	0.24	0.28	0.35	0.44	0.53	0.62	0.70	0.98	–
Stainless steel	5	0.10	0.15	0.20	0.25	0.28	0.30	0.42	0.41	–	–	–	–
	15	0.10	0.15	0.19	0.25	0.30	0.34	0.45	0.51	0.60	–	–	–
	25	0.10	0.14	0.20	0.26	0.31	0.33	0.43	0.50	0.62	–	–	–
Brass	5	0.08	0.12	0.18	0.25	0.21	0.22	0.25	0.28	–	–	–	–
	15	0.10	0.14	0.20	0.28	0.28	0.29	0.35	0.41	0.44	0.48	0.55	–
	25	0.10	0.15	0.20	0.25	0.28	0.30	0.36	0.43	0.46	0.50	0.53	–
Aluminum	5	0.09	0.15	0.19	0.23	0.28	0.30	0.41	0.40	–	–	–	–
	15	0.10	0.15	0.19	0.26	0.29							