


Please read this operating manual carefully. Correct assembly and handling of the tool will save you set-up time and allow you to achieve optimal results.

1. Basics of burnishing

This process is a smooth rolling process. A diamond installed in the head of the tool glides over the workpiece and shapes the existing rough ness profile. If the flow limit of the material is reached, cold deformation of the edge layer begins and existing rough peaks flow into adjacent recesses and are thereby levelled out and compacted. This produces a smooth and resistant surface (Fig. 1). Treatment of hardened and highstrength materials is possible







0 0 (6)




Figure 3: Exploded diagram of CNC-lathe version GW520-16U

Figure 4: Exploded diagram of Swiss-type lathe version GW520-10R

This tool can be used on all machine versions.

Note: Left version of the tool (Swiss-type lathe variant) is available on request!

Note: Diamond tips are not included in the scope of delivery.

The following tip dimensions (Fig. 2) can be purchased separately: R0.4 mm $(X=53^{\circ})/R0.6$ mm $(X=62^{\circ})/R0.8$ mm $(X=62^{\circ})/R1.0$ mm $(X=62^{\circ})$

2. Tool setting

1. Clamping position of tool

Clamp the tool at an angle of 90° to the workpiece. The centre height is the top edge of the shank.

2.) Diamond tip assembly

To assemble or change the diamond tip, the threaded pin must be released first (Fig. 5, Pos. 5). Then the tip (Fig. 5, Pos. 9) can be removed. During assembly, it must be ensured that the diamond tip is aligned correctly and is clamped on the clamping surface by the threaded pin.

3 Turning of the diamond tip

If signs of wear appear on the diamond tip, the complete guide axis can be turned up to four times in order to enable further use of the tip. Therefore loosen the threaded pin (Fig. 5, Pos. 10), remove the diamond tip, $\,$ rotate it 90 $^{\circ}$ and insert again. Then tighten the threaded pin.

In addition the guide axis (Fig. 8, Pos. 3) can also be turned once.

For this purpose, the Locking screw (Fig. 6, Pos. 4) must be completely unscrewed with the accompanying key (Art. no.: 22BHRO335). In this case, rotation of the guide axis is desired. Then the guide axis and diamond tip can be removed, rotated 45° (from the notch marked red to the notch marked blue) (e.g. Fig. 8) and inserted again. Ensure that the notch of the guide axis is guided through the upper cylinder pin (Fig. 8, Pos. 11) in the base holder.

Then the adjusting screw can be screwed into the base holder again and the system can be clamped. If both options are combined, the diamond tip can be used up to eight times.

> -Turning of the diamond tip is possible up to three times! -Turning of the guide axis is possible once!

4. Replace the spring assambly

In order to replace the spring assembly in case if wear, please loosen the adjusting screw (Fig. 6, item 4) first. Then the guide axis (Fig. 8, item 3) and the spring assembly (Fig. 8, item 8) can be removed

When reassembling, make sure that the spring assembly is threaded onto the attach-

ment of the guide axis. Note: The standard set-up of spring assambly is in pictures on Figure 7




Figure 5: Diamond tip assembly

2

11

Figure 7: Spring assembly

Finally return the guide axis back into basic holder and screw the adjusing screw as far as it willgo and the system tensioned.

3. Use

Note:

000

Necessary preparation

The workpiece must have an even roughness profile with a pre-turn surface of Rz10 (Ra1.0) to Rz20 (Ra2.0).

Tolerance fluctuations during preparation on the workpiece should be minimised. - The finer the pre-turn surface of the workpiece, the finer the burnished surface will be

- The concentricity of the workpiece must be max. 0.03 mm.

2 Approaching the workpiece

After the preliminary work has been carried out, the tool can be approached and scratched on the workpiece (see Fig. 10). The infeed takes place in a diagonal direction (depending on the inclination of the tool head) and may only be a few hundredths. The next step is to apply the spring force.

3. Application of spring force with infeed in the machining direction The infeed corresponds to the applied spring stroke and is based on the desired target surface quality and the material to be machined (e.g. Table. 1).

The approach must take place on the workpiece and not in front of it! (e.g. Fig. 10) -The maximum stroke of the tip must not exceed 1.8-2 mm.

Please use the infeed value of the table (mm) for the setting in x-direction and the Feed rate f (mm/rev) for moving in z-direction (Figure 10). The values can vary depending on different materials The recommende dwell time for a clean burnishing result maximum 3-10 revolutions of the workpiece

- These specifications are guideline values based on an initial surface of Rz10 (Ra1)
- The optimal setting must be determined in the process. - For contour transitions, ensure a steady contact pressure of the diamond tip (Fig. 11).

4. Cutting data

IMPORTANT

The cutting data of the burnishing process should be based on the finishing of the turning with which the workpiece was prepared. The radius of the diamond-tip should be larger than the radius of the turning inserts.



Figure 10: Approach of workpiece



Figure 8: Turning of the guide axis

3

8

(5.) Tool head adjustment

With this tool type, the tool head can be pivoted $\pm 90^{\circ}$ (Fig. 9). Then contours of convex and concave geometries can also be machined. To adjust the head, first loosen the hexagon screw (Fig. 3 + Fig. 4, item 7). Then the head can be swiveled in the desired direction using the engraved scale. Once the desired position of the head has been achieved retighten the hexagon socket screw.

Note: Only unscrew the hexagon screw until it is possible to turn the tip

Note: A slight incline of the tool head (approx. 10-20° towards the tool spindle) is recommended for a consistent material flow during machining of cylindrical components. With deviating contours, the tool head setting must be adjusted




Figure 9: Tool head adjustment

6. Spring pressure

The spring force is applied via the infeed in the machine (see Chapter 3, Reference 3). Guide values for the machining parameters of different materials can be rechecked in Figure 12.

Please do not change the delivered set-up of spring assembly for standard burnishing applications.

4. Manufacturer's recommendations

Continuous cooling by means of emulsion or oil is recommended.

Replace the diamond tip after the appropriate number of cycles, after considerable wear or in case of deviating process parameters, and/or after turning the guide axis three times. Machining of interrupted cuts must be avoided. Values in Table 1 refer to an initial surface of Rz5 - Rz10

values in tuble 1 felet to an initial surface of K25 - K210			
Material	Cutting speed vc [m/ min]	Feed rate f [mm/U]	Infeed ap [mm]
Quenched and tempe- red steel	100 - 130	0,02 - 0,1	0,01 - 0,08
Stainless steel	100 -130	0,02 - 0,06	0,01 - 0,1
Cast iron	80 - 120	0,05 - 0,1	0,05 - 0,2
Free cutting steel	110 - 140	0,02 - 0,06	0,006 - 0,04
Brass	100 - 130	0,02 - 0,06	0,005 - 0,02
Aluminium	120 - 140	0,03 -0 ,1	0,005 - 0,02

Table 1: Guide values for the machining paramters

Deviations of up to 20% can arise due to tolerances of individual materials. If the spring stroke is too high in case of infeed high pressures can be achieved. However, this can result in a rlower surface quality

The optimal setting must be determined in the process.

